



## ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

ಆರೋಗ್ಯ ವೈದ್ಯಾಧಿಕಾರಿಗಳ ಕಛೇರಿ, ಸರ್ವಜ್ಞನಗರ ವಿಭಾಗ, ಸೂರ್ವ ವಲಯ, ಕಾಕ್ಸಾಟಾನ್, ಬೆಂಗಳೂರು

ಆ.ವೈ.ಸ.ನ/ಪಿ.ಆರ್/337/2024-25

ದಿನಾಂಕ: 04-04-2024

### Sub:- PROFORMA REGARDING SAFE DRINKING WATER AND SANITARY CONDITION CERTIFICATE

It is certified that an inspection learn headed by medical officer of health from Sarvagnanagar BBMP inspected the ST.JOHNS INTERNATIONAL SCHOOL, No.71, Pillamma Road, Behind Jalvayu Vihar, HRBR Layout, Kacharakanahalli, Bangalore-560084 run by N P MEMORIAL TRUST ® on the basis of water Test Report (attached) bearing no PHI/Water/BAC/1090/23-24 dated: 26.03.2024 of office of joint Director, Public Health Institute certified that the ST.JOHNS INTERNATIONAL SCHOOL, No.71, Pillamma Road, Behind Jalvayu Vihar, HRBR Layout, Kacharakanahalli, Bangalore-560084, has safe drinking water facilities for the students and members of staff of the institution, school also maintain the hygienic condition in the School building and the campus as per norms prescribed by the Central/state/U.TGovernment.

This Certificate is Valid From 04-04-2024 to 03-04-2025

  
Medical Officer of the Health  
Bruhat Bengaluru Mahanagara Palike  
Bangalore-560 084

To,  
ST.JOHNS INTERNATIONAL SCHOOL,  
No.71, Pillamma Road,  
Behind Jalvayu Vihar,  
HRBR Layout,  
Kacharakanahalli, Bangalore-560084

(TRANSLATION FROM KANNADA TO ENGLISH)

SEAL OF BBMP BENGALURU-  
560005, SARVAGNANAGAR

**BRUHATH BANGALORE MAHANAGARA PALIKE**  
HEALTH MEDICAL OFFICER OFFICE, SARVAGNANAGAR DIVISION, EAST  
ZONE, COX TOWN, BANGALORE

No. A.Y.S.N./P.R./337/2023-24

Date: 04.04.2024

**Sub : PROFORMA REGARDING SAFE DRINKING WATER AND  
SANITARY CONDITION CERTIFICATE**

It is certified that an inspection team head by medical officer of health from Sarvagnanagar BBMP inspected the **ST.JOHNS INTERNATIONAL SCHOOL**, No. 71, Pillamma Road, Behind Jalvayu Vihar, HRBR Layout, Kacharakannahalli, Bangalore – 560084 run by **N P MEMORIAL TRUST \*** on the basis of Water Test Report (attached) bearing no PHI/Water/BAC/1090/23-24 dated: 26.03.2024 of Office of Joint Director, Public Health Institute certified that the the **ST.JOHNS INTERNATIONAL SCHOOL**, No. 71, Pillamma Road, Behind Jalvayu Vihar, HRBR Layout, Kacharakannahalli, Bangalore – 560084, has safe drinking water facilities for the students and members of staff of the institution, School also maintains the hygienic condition in the School building and the campus as per the norms prescribed by the Central/State/U.T.Government

This certificate is Valid From 04-04-2024 to 03-04-2025

Sd/-  
**MEDICAL OFFICER HEALTH**  
SARVAGNANAGAR  
Bangalore Mahanagara Palike  
BANGALORE 560005

To  
**ST.JOHNS INTERNATIONAL SCHOOL,**  
No. 71, Pillamma Road,  
Behind Jalvayu Vihar,  
HRBR Layout,  
Kacharakannahalli, Bangalore – 560084

TRANSLATED BY ME:



ATTESTED BY ME  
*Ratna.N.*  
**RATNA.N.**  
Bcom, J.L.L.  
Advocate & Notary Public  
GOVT. OF INDIA  
No. 5001 B, Shree Complex, 8th Main 4th Stage,  
Basaveshwaranagar, Bangalore - 560 079  
Mob : 98801 96680  
12/4/24

GOVERNMENT OF KARNATAKA

Office of the Joint Director  
Public Health Institute  
Bengaluru - 560 001

Dated: 26-03-2024

Report of Bacteriological analysis of Water/Effluent sample

Sample No.	Source & Particulars of Water Sample	Opinion				
		M.P.N Count	Plate Count	D.C Test	S.P.P	N.S.P.P & FC.
3408	RO water	Nil	-	-	SPP	-
	B.No. 4129986					
<p><i>Princimax</i></p> <p><i>Sd. Johns International</i></p> <p><i>School: # 71.</i></p> <p><i>Pillaranna road,</i></p> <p><i>Behind jai veeru vidyalaya</i></p> <p><i>HRBB lay out. B-8A</i></p> <p>Note: M.P.N Count: Most probable number of Bacteria per 100ml of Water D.C Test: Differential Colliform test Plate Count: Plate Count per ml of sample SPP: Water is satisfactory for Potable purpose NSPP: Water is not satisfactory for Drinking purpose NSPP &amp; FC: Water is not satisfactory for Drinking purpose and E.Coli found</p>						

For Joint Director (Labs)  
PUBLIC HEALTH INSTITUTE  
Bengaluru  
(PTO)

No:PHI/Water/BAC/1090/23-24