

(TRANSLATION FROM KANNADA TO ENGLISH)

Office of the Assistant Executive Engineer
No. 1, Building Sub-Division,
V.V. Centre, Bengaluru

Logo Of Government Of Karnataka
Government Of Karnataka
Public Works Department

Phone 22863305
e-mail : aee1vvtower@gmail.com

No. AEE/No.1BSD/A.E-1/2022-23/1397

Date : 27/02/2023

To
The Principal,
St. Johns International School,
No. 71, Pillamma Road,
Behind Jal Vayu Vihar,
HRBR Layout, Kacharaknahalli,
St. Thomas Town Post,
Bangalore-560084

SEAL
Office of the Assistant Executive Engineer
No. 1, Building Sub-Division
Dr. Ambedkar Road
Bengaluru - 560001
No. 1397
Date : 27/02/2023

Sir,

Sub : Regarding issue of Renewal Building Safety Certificate for
St. Johns International School

Reference : 1. Letter from St. Johns International School, Bangalore
dated: 21-02-2023

2. Government Order No.: P.W.D/59/B.E.D./2019/ Dated: 06-05-2022.

As per the above subject, St. Johns International School, No. 71, Pillamma Road, Behind Jal Vayu Vihar, HRBR Layout, Kacharaknahalli, St. Thomas Town Post, Bangalore-560084 you have requested for Building Safety Certificate for the School Building purpose in Reference (1). and have submitted all the documents to this office.

According to the Government order in reference (2) rule the School building of St. Johns International School has been inspected on Date : 24-02-2023 in presence of the Concerned Head and the said Fee of amount Rs. 5000.00/- (Rupees Five Thousand Only) for the issue of Building safety certificate has been paid vide DD. No. : 053303 Dated : 27-02-2023 drawn from HDFC Bank has been submitted to this office

The School building infrastructure has 01 Play room, Computer Lab, 01 Library, 01 A.V. Room in the Basement. The Ground Floor has 03 Classrooms, 01 Administrative Office, 01 Sick Room, 01 Principal Cabin, 02 Toilets. The First Floor has 06 Classrooms, 02 Toilets. The Second Floor has 07 Classrooms, 01 Lab, 01 Staff Room, 02 Toilets. The Third Floor has 01 Hall.

- The said building St. Johns International School, No. 71, Pillamma Road, Behind Jal Vayu Vihar, HRBR Layout, Kacharaknahalli, St. Thomas Town Post, Bangalore-560084 has been observed that its been built, the ownership of the building is in the name of N. Kupendra, Bangalore. The said building has been built in the year 2020.



- The safety of the building and strength of building concrete and Rebound hammer test & Ultra Sonic test has been done on Date : 16-02-2023 and a report has been submitted by M/s. S.R. Consultants and Engineers, No. 8, 1st Cross, 2nd Main, Annapoorneshwari layout, Near Maruthi School, Bangalore – 560062.
- The Annexure -1 to 6 has been submitted.

All the documents submitted by the Institution has been examined, Safety Check report, Physical observation, Investigating studies, Rebound hammer test, Ultra Sonic test report, Ultra Sonic pulse velocity test have also been conducted and M/s. S.R. Consultants and Engineers, Bangalore have submitted a certificate stating that the Building construction is safe. The said report and Building observing that the building's R.C.C. Column, Beam and Ceiling has no cracks and looking at the building it is found to be safe. And found that the Building Structural Sound Condition in the inspection report and looking at the building it is found to be safe. The following conditions have to be followed.

1. All the necessary Permission/Certificates following the rules and within the timeline has to be obtained from The Fire and Emergency services and other related departments from the concerned authority.
2. The building has to be repaired using good quality materials and with the help of experts from time to time.
3. All the necessary safety measures has to implemented for the safety of the Teachers and students .
4. Any building modification which will cause harm to the structure of the building has to be started with the permission of the concerned capable authorities and in case it is been done without the permission then this Certificate is cancelled immediately.
5. The Cleanliness of the Drinking water and Toilets has to be safeguarded and related to Bruhat Bangalore Mahanagara Palike all the necessary directions and rules of the School and College has to be strictly followed.


The Building safety Certificate has been issued to St. Johns International School, No. 71, Pillamma Road, Behind Jal Vayu Vihar, HRBR Layout, Kacharaknahalli, St. Thomas Town Post, Bangalore-560084 considering they follow the above mentioned conditions.

Yours faithfully

Sd/-

Assistant Executive Engineer
No. 1, Building Sub-Division,
Bangalore

Translated by Me :



ATTESTED BY ME
Ratna N.
RATNA. N.
B.Com., LL.B.
Advocate & Notary Public
GOVT. OF INDIA
No. 500/B, Shree Complex, 8th Main, 4th Stage,
Basaveshwaranagar, Bengaluru-560 079
Mob : 98801 96680

21 FEB 2026



ಲೋಕೋಪಯೋಗಿ ಇಲಾಖೆ

ಸಂ: ಸಕಾಇಂ/ನಂ.1ಕ.ಉ.ವಿ/ಎ.ಇ-1/2022-23/1397

ದಿನಾಂಕ: 27/02/2023

To,
The Principal,
St. Johns International School,
No. 71, Pillamma Road,
Behind Jal Vayu Vihar,
HRBR Layout, Kacharaknahalli,
St. Thomas Town Post,
Bangalore - 560084.



ಮಾನ್ಯರೇ,

ವಿಷಯ : St. Johns International School, ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡುವ ಬಗ್ಗೆ.
ಉಲ್ಲೇಖ :1) St. Johns International School, Bangalore ರವರ ಪತ್ರ ದಿನಾಂಕ: 21-02-2023
2) ಸರ್ಕಾರದ ಆದೇಶ ಸಂಖ್ಯೆ: ಲೋ.ಇ/59/ಬಿ.ಇ.ಡಿ/2019/ದಿನಾಂಕ: 06-05-2022.

* * * * *

ಮೇಲ್ಕಂಡ ವಿಷಯಕ್ಕೆ ಸಂಬಂಧಿಸಿದಂತೆ, St. Johns International School, No. 71, Pillamma Road, Behind Jal Vayu Vihar, HRBR Layout, Kacharaknahalli, St. Thomas Town Post, Bangalore, ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ಶೈಕ್ಷಣಿಕ ಉದ್ದೇಶಕ್ಕಾಗಿ ಒದಗಿಸಲು ಅಗತ್ಯವಿರುವುದಾಗಿ ತಿಳಿಸಿ ಕಟ್ಟಡದ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರ ನೀಡಲು ಉಲ್ಲೇಖ (1)ರ ತಮ್ಮ ಪತ್ರದಲ್ಲಿ ಕೋರಲಾಗಿರುತ್ತದೆ. ಹಾಗೂ ಸದರಿ ಕಟ್ಟಡಕ್ಕೆ ಸಂಬಂಧಿಸಿದ ದಾಖಲೆಗಳನ್ನು ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸಲಾಗಿರುತ್ತದೆ.

ಅದರಂತೆ, ಶಾಲಾ ಕಟ್ಟಡವನ್ನು ದಿನಾಂಕ: 24-02-2023 ರಂದು St. Johns International School, ಮುಖ್ಯಸ್ಥರ ಉಪಸ್ಥಿತಿಯಲ್ಲಿ ಪರಿವೀಕ್ಷಿಸಲಾಗಿರುತ್ತದೆ. ಹಾಗೂ ಉಲ್ಲೇಖ (2)ರ ಸರ್ಕಾರದ ಆದೇಶದನ್ವಯ ನಗರ ಪ್ರದೇಶದಲ್ಲಿನ ಶಾಲೆಯ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲು The Assistant Executive Engineer, No. 1 Buildings Sub-division, V.V. Centre, Bangalore ರವರ ಹೆಸರಿನಲ್ಲಿ ರೂ. 5000/- ಮೊತ್ತದ ಹೆಚ್.ಡಿ.ಎಫ್.ಸಿ. ಬ್ಯಾಂಕ್‌ನ ಡಿ.ಡಿ. ಸಂಖ್ಯೆ: 053303/ ದಿನಾಂಕ: 27-02-2023 ನ್ನು ಈ ಕಛೇರಿಗೆ ಸಲ್ಲಿಸಿರುತ್ತೀರಿ.

ಶಾಲಾ ಕಟ್ಟಡದ ಸಂಕೀರ್ಣವು ತಳ ಮಹಡಿಯಲ್ಲಿ 01 ಆಟದ ಕೊಠಡಿ, ಕಂಪ್ಯೂಟರ್ ಲ್ಯಾಬ್, 01 ಲೈಬ್ರರಿ, 01 ಎ.ವಿ. ರೂಂ ಇರುತ್ತದೆ. ನೆಲಮಹಡಿಯಲ್ಲಿ 03 ತರಗತಿ ಕೊಠಡಿಗಳಿದ್ದು, 01 ಆಡಳಿತ ಕಛೇರಿ, 01 ಸಿಕ್ ರೂಂ, 01 ಪ್ರಾಂಶುಪಾಲರ ಕೊಠಡಿ, 02 ಶೌಚಾಲಯವಿರುತ್ತದೆ. ಮೊದಲನೇ ಮಹಡಿಯಲ್ಲಿ 06 ತರಗತಿ ಕೊಠಡಿಗಳಿದ್ದು, 02 ಶೌಚಾಲಯವಿರುತ್ತದೆ. ಎರಡನೇ ಮಹಡಿಯಲ್ಲಿ 07 ತರಗತಿ ಕೊಠಡಿಗಳಿದ್ದು, 01 ಲ್ಯಾಬ್, 01 ಸಿಬ್ಬಂದಿಗಳ ಕೊಠಡಿಗಳಿದ್ದು, 02 ಶೌಚಾಲಯವಿರುತ್ತದೆ. ಮೂರನೇ ಮಹಡಿಯಲ್ಲಿ 01 ಹಾಲ್ ಇರುತ್ತದೆ.

- ಸದರಿ ಕಟ್ಟಡವನ್ನು St. Johns International School, No. 71, Pillamma Road, Behind Jal Vayu Vihar, HRBR Layout, Kacharaknahalli, St. Thomas Town Post, Bangalore - 560084 ರಲ್ಲಿ

ನಿರ್ಮಿಸಿರುವುದು ಕಂಡು ಬಂದಿದ್ದು, ಸದರಿ ಕಟ್ಟಡದ ಮಾಲೀಕತ್ವವನ್ನು N. Kupendra, Bangalore. ರವರ ಹೆಸರಿನಲ್ಲಿರುತ್ತದೆ. ಸದರಿ ಕಟ್ಟಡವನ್ನು 2020ನೇ ಸಾಲಿನಲ್ಲಿ ನಿರ್ಮಿಸಲಾಗಿರುತ್ತದೆ.

- ಕಟ್ಟಡದ ಸುರಕ್ಷತೆಗೆ ಸಂಬಂಧಿಸಿದಂತೆ ಕಟ್ಟಡದ ಕಾಂಕ್ರಿಟ್ ಸದೃಢತೆಯ ಬಗ್ಗೆ ದಿನಾಂಕ: 16-02-2023 ರಲ್ಲಿ M/s. S. R. Consultants and Engineers, No. 8, 1st Cross, 2nd Main, Annapoorneshwari layout, Near Maruthi School, Bangalore – 560062 ರವರು Rebound hammer test & Ultra Sonic test ಕೈಗೊಂಡು ವರದಿಯನ್ನು ನೀಡಿರುತ್ತಾರೆ.
- ಅನೇಕ್-1 ರಿಂದ 6 ನ್ನು ಸಲ್ಲಿಸಲಾಗಿರುತ್ತದೆ.

ಸದರಿ ಸಂಸ್ಥೆಯವರು ನೀಡಿರುವ ಎಲ್ಲಾ ದಾಖಲೆಗಳನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ, Safety Check report, Physical observation, Investigating studies, Rebound hammer test, Ultra Sonic test report, Ultra Sonic pulse velocity test ಗಳನ್ನೂ ಸಹ ಕೈಗೊಂಡಿರುತ್ತಾರೆ. ಹಾಗೂ M/s. S. R. Consultants and Engineers, Bangalore ರವರು ಕಟ್ಟಡವು ರಚನಾತ್ಮಕವಾಗಿ ಸುರಕ್ಷಿತವಾಗಿದೆಯೆಂದು ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಿರುತ್ತಾರೆ. ಸದರಿ ವರದಿಗಳನ್ನು ಹಾಗೂ ಕಟ್ಟಡವನ್ನು ಪರಿಶೀಲಿಸಲಾಗಿ ಕಟ್ಟಡದ ಆರ್.ಸಿ.ಸಿ. ಕಂಬ, ತೊಲೆ ಹಾಗೂ ಛಾವಣಿಯಲ್ಲಿ ಯಾವುದೇ ಬಿರುಕುಗಳು ಕಂಡು ಬಂದಿರುವುದಿಲ್ಲ ಹಾಗೂ ಕಟ್ಟಡವು ಮೇಲ್ನೋಟಕ್ಕೆ ಸುರಕ್ಷಿತವಾಗಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಹಾಗೂ ಕಟ್ಟಡವು Structural Sound Condition ಇರುವುದಾಗಿ ಪರೀಕ್ಷೆ ವರದಿಗಳು ಕಂಡು ಬಂದಿರುವುದರಿಂದ ಹಾಗೂ ಕಟ್ಟಡವು ಮೇಲ್ನೋಟಕ್ಕೆ ಸುರಕ್ಷಿತವಾಗಿರುವುದು ಕಂಡು ಬಂದಿರುತ್ತದೆ. ಈ ಕೆಳಕಂಡ ಷರತ್ತುಗಳನ್ನು ಅನುಸರಿಸಲು ಸೂಚಿಸಲಾಗಿದೆ.

1. ಅಗ್ನಿಶಾಮಕ ಇಲಾಖೆ ಮತ್ತು ಇತರೆ ಸಂಬಂಧಪಟ್ಟ ಇಲಾಖೆಗಳ ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರಗಳಿಂದ ಅನುಮತಿ / ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನಿಯಮಾವಳಿಗಳ ಅನ್ವಯ ನಿಗದಿತ ಸಮಯಗಳಲ್ಲಿ ಪಡೆಯತಕ್ಕದ್ದು.
2. ಕಟ್ಟಡವನ್ನು ಕಾಲಕಾಲಕ್ಕೆ ಉತ್ತಮ ಗುಣಮಟ್ಟದ ಸಾಮಗ್ರಿಗಳನ್ನು ಬಳಸಿ ತಜ್ಞರಿಂದ ವ್ಯವಸ್ಥಿತವಾಗಿ ನಿರ್ವಹಣೆ ಮಾಡತಕ್ಕದ್ದು.
3. ವಿದ್ಯಾರ್ಥಿಗಳ ಹಾಗೂ ಶಿಕ್ಷಕರ ಸುರಕ್ಷತೆಗೆ ಸಕಲ ಆದ್ಯತೆಯನ್ನು ನೀಡಿ ಸೂಕ್ತ ಸುರಕ್ಷತಾ ವ್ಯವಸ್ಥೆಯನ್ನು ಅಳವಡಿಸಿಕೊಳ್ಳತಕ್ಕದ್ದು.
4. ಕಟ್ಟಡದ ಸದೃಢತೆಗೆ ಧಕ್ಕೆಯಾಗುವಂತಹ ಯಾವುದೇ ಇತರೆ ಕಾಮಗಾರಿಗಳನ್ನು ಸಕ್ಷಮ ಪ್ರಾಧಿಕಾರದಿಂದ ಅನುಮತಿ ಪಡೆಯದೇ ಕೈಗೊಳ್ಳತಕ್ಕದ್ದಲ್ಲ. ಅನುಮತಿ ಪಡೆಯದೇ ಕೈಗೊಂಡಲ್ಲಿ ಪ್ರಮಾಣ ಪತ್ರವು ಆ ಕೂಡಲೇ ರದ್ದಾಗುತ್ತದೆ.
5. ಕುಡಿಯುವ ನೀರು ಹಾಗೂ ಶೌಚಾಲಯಗಳಲ್ಲಿ ಸದಾ ಸ್ವಚ್ಛತೆಯನ್ನು ಕಾಪಾಡಿಕೊಳ್ಳತಕ್ಕದ್ದು ಹಾಗೂ ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆಯಿಂದ ಶಾಲಾ ಕಾಲೇಜಿಗೆ ಸಂಬಂಧಿಸಿದ ಎಲ್ಲಾ ನಿರ್ದೇಶನ ಹಾಗೂ ನಿಯಮಾವಳಿಯನ್ನು ಕಡ್ಡಾಯವಾಗಿ ಪಾಲಿಸತಕ್ಕದ್ದು.

ಮೇಲೆ ತಿಳಿಸಲಾಗಿರುವ ಷರತ್ತುಗಳಿಗೊಳಪಟ್ಟು St. Johns International School, No. 71, Pillamma Road, Behind Jal Vayu Vihar, HRBR Layout, Kacharaknahalli, St. Thomas Town Post, Bangalore – 560084 ಕಟ್ಟಡಕ್ಕೆ ಸುರಕ್ಷತಾ ಪ್ರಮಾಣ ಪತ್ರವನ್ನು ನೀಡಲಾಗಿದೆ.

ತಮ್ಮ ವಿಶ್ವಾಸಿ,

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ನಂ. 1 ಕಟ್ಟಡಗಳ ಉಪವಿಭಾಗ, ಬೆಂಗಳೂರು.